



Assembly Instruction

product: PMA-EC-912-PMB-VA0.x/VA1.x/VA2.x
author: S. Weber
date: Apr. 29, 2025
doc ID: 250429-PT95MA-SW-PMA-EC-912
PMB-VA0.x,VA1.x,VA2.x_rev.00.idw
passing:



INTRO



What you need:	
Wrench	17mm
Torque wrench	17mm
Pole Ø	50mm to 105mm

ATTENTION:
Please be careful when
working at heights !






table of content			
obj.	qty.	part	material
1	2	PMB-VA1/2	stainless steel
2	4	Threaded rod M10x1,5x210	stainless steel
3	12	Nut ISO 4032 - M10	stainless steel
4	16	Washer DIN 125 - A 10,5	stainless steel
5	4	Threaded bolt ISO 4017 - M10 x 25	stainless steel

1


*External equipment
Please mount first!*




2






3



4





Note:
For more information see
other assambly instructions!



