



Assembly Instruction

product: CMA-EC-962-CMB-TNXCD/VA4.x

author: S. Weber


date: Apr. 30, 2025

doc ID: 250430-PT95MA-SW-CMA-EC-962-CMB-TNXCD,VA4.x_assembly
instruction_rev.oo.idw

passing:



INTRO



What you need:	
Wrench	13mm
Torque wrench	13mm

ATTENTION:
Please be careful when working at heights !



*Not-included fastening parts required!
Threaded bolts M10 for individual ceiling mount*





Table of content			
obj.	qty.	part	material
1	1	CMB VA4 - TNXCD part I	stainless steel
2	1	CMB VA4 - TNXCD part II	stainless steel
3	5	Threaded bolt ISO 4017 - M8 x 16	stainless steel
4	9	Washer DIN 125 - A 8,4	stainless steel
5	4	Threaded bolt ISO 4017 - M8 x 12	stainless steel


1

Fix to ceiling or to PMB!




2


tightening: 15Nm




3



4





5





tightening: 15Nm

6






VA4 housing



TNXCD housing





Note:
For more information see
other assambly instructions!

