



Assembly Instruction


product: PMA-EC-962-PMB-TNXCD/To8-VA4.x
author: S. Weber
date: Apr. 30, 2025
doc ID: 250430-PT95MA-SW-PMA-EC-962-PMB-TNXCD,
To8-VA4.x_assembly instruction_rev.00.idw
passing:



INTRO



What you need:	
Wrench	19mm
Wrench	17mm
Torque wrench	17 - 19mm
Pole Ø	100mm to 150mm




ATTENTION:
Please be careful when
working at heights !



Table of content			
obj.	qty.	part	material
1	2	PMB-TNXCD	stainless steel
2	8	Washer DIN 125 - A 13	stainless steel
3	8	Nut ISO 4032 - M12	stainless steel
4	4	Threaded rod M12 x 1.5 x 260	stainless steel
5	4	Threaded bolt ISO 4017 - M10 x 25	stainless steel
6	8	Washer DIN 125 - A 10,5	stainless steel
7	4	Nut ISO 4032 - M10	stainless steel


1

*External equipment
Please mount first!*




2


tightening: 25Nm






3



4







Note:

For more information see
other assembly instructions!



