



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

QAR Ref. No.:	DE/BVS/QAR06.0007/15	Page 1 of 2
QAR Free Ref. No.:	ZQS/E142/24	Status: Issued
Details of change:	Type protection "p" was added.	Date of issue: 2024-03-04
Location(s) audited:	R. STAHL HMI Systems GmbH Adolf-Grimme-Allee 8 50829 Köln Germany	Valid until: 2025-01-30 Audit date: 2024-02-20
Issuing ExCB:	BVS - DEKRA Testing and Certification GmbH	
Manufacturer:	R. STAHL HMI Systems GmbH Adolf-Grimme-Allee 8 50829 Köln	
Location of Manufacturer:	Germany	
Product information:	Operating and monitoring equipment and systems.	
Type of protection:	Powder filling "q" Flameproof enclosures "d" Pressurized enclosure "p" Increased safety "e" Intrinsic safety "i" Type of protection "nA", "nC", "nR" Encapsulation "m" Optical radiation "op is/pr/sh" Protection by enclosure "t"	

Related QARs:

DE/BVS/QAR06.0007/00	DE/BVS/QAR06.0007/01	DE/BVS/QAR06.0007/02
DE/BVS/QAR06.0007/03	DE/BVS/QAR06.0007/04	DE/BVS/QAR06.0007/05
DE/BVS/QAR06.0007/06	DE/BVS/QAR06.0007/07	DE/BVS/QAR06.0007/08
DE/BVS/QAR06.0007/09	DE/BVS/QAR06.0007/10	DE/BVS/QAR06.0007/11
DE/BVS/QAR06.0007/12	DE/BVS/QAR06.0007/13	DE/BVS/QAR06.0007/14

Related Certificates (manual insertion)::

IECEX BVS 05.0001 issue: 0 [Current]

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEX BVS 06.0015 issue: 0	IECEX BVS 06.0015 issue: 2	IECEX BVS 07.0002 issue: 0
IECEX BVS 07.0002 issue: 1	IECEX BVS 07.0002 issue: 2	IECEX BVS 08.0031 issue: 0
IECEX BVS 08.0031 issue: 1	IECEX BVS 08.0032 issue: 0	IECEX BVS 08.0032 issue: 1
IECEX BVS 08.0032 issue: 4	IECEX BVS 08.0044 issue: 0	IECEX BVS 08.0044 issue: 1
IECEX BVS 09.0012 issue: 0	IECEX BVS 09.0012 issue: 1	IECEX BVS 09.0012 issue: 2
IECEX BVS 10.0094 issue: 0	IECEX BVS 10.0094 issue: 1	IECEX BVS 10.0094 issue: 2
IECEX BVS 10.0094 issue: 3	IECEX BVS 11.0058X issue: 1	IECEX BVS 11.0075X issue: 0
IECEX BVS 11.0075X issue: 1	IECEX BVS 12.0053 issue: 0	IECEX BVS 12.0088X issue: 0
IECEX BVS 13.0038 issue: 0	IECEX BVS 13.0040X issue: 0	IECEX BVS 14.0034X issue: 0
IECEX BVS 14.0116X issue: 0	IECEX BVS 14.0116X issue: 1	IECEX BVS 14.0116X issue: 2
IECEX BVS 15.0039X issue: 0	IECEX BVS 15.0039X issue: 1	IECEX BVS 16.0088 issue: 0
IECEX BVS 17.0097X issue: 0	IECEX BVS 18.0001 issue: 0	IECEX BVS 18.0026U issue: 0
IECEX BVS 20.0065X issue: 0	IECEX BVS 20.0084X issue: 0	IECEX IBE 14.0002 issue: 0
IECEX IBE 14.0003 issue: 0	IECEX IBE 16.0002 issue: 0	IECEX IBE 16.0002 issue: 1
IECEX IBE 16.0002 issue: 2	IECEX IBE 16.0003 issue: 0	IECEX IBE 16.0003 issue: 1
IECEX IBE 16.0003 issue: 2	IECEX IBE 16.0004 issue: 0	IECEX IBE 16.0004 issue: 1
IECEX IBE 16.0004 issue: 2	IECEX IBE 16.0004 issue: 3	IECEX ITS 16.0026X issue: 1
IECEX ITS 16.0026X issue: 2	IECEX ITS 16.0026X issue: 3	IECEX KEM 09.0039X issue: 0
IECEX KEM 09.0039X issue: 3	IECEX LCIE 14.0011X issue: 1	IECEX PTB 16.0032X issue: 0
IECEX PTB 16.0032X issue: 1	IECEX SIR 16.0057 issue: 0	IECEX SIR 16.0057 issue: 1
IECEX SIR 16.0057 issue: 2	IECEX SIR 16.0057 issue: 3	IECEX SIR 16.0057 issue: 4

-- Continued on the next page



IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/BVS/QAR06.0007/15**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEX SIR 16.0057 issue: 5
IECEX TUR 11.0006X issue: 3
IECEX ULD 16.0005X issue: 2
IECEX ULD 16.0005X issue: 5
IECEX ULD 18.0001X issue: 1

IECEX SIR 16.0057 issue: 6
IECEX TUR 13.0005 issue: 1
IECEX ULD 16.0005X issue: 3
IECEX ULD 16.0005X issue: 6

IECEX TUR 09.0005X issue: 0
IECEX UL 23.0007X issue: 0
IECEX ULD 16.0005X issue: 4
IECEX ULD 18.0001X issue: 0

Comments: