

IS1+ Detect - Software Release Notes

V 3.0.0		Release Date	22.01.2024
New Features	<ul style="list-style-type: none"> • Password protection for settings • Change of protocol IP address • Time sync with PC • NTP settings • License file handling (e.g. for OPC UA) • Factory reset • Encryption for whole communication • Displays all MAC addresses 		
Bugfix	<ul style="list-style-type: none"> • Assignment of redundant CPUs 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • New features only with firmware version V01.01.04 and above 		

V 2.1.1		Release Date	12.08.2021
New Features	<ul style="list-style-type: none"> • Add maintenance string "Redundant PM observation deactivated" 		
Bugfix	<ul style="list-style-type: none"> • 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.1.0		Release Date	09.07.2021
New Features	<ul style="list-style-type: none"> • Show socket serial number 		
Bugfix	<ul style="list-style-type: none"> • 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.0.7		Release Date	15.04.2021
New Features	<ul style="list-style-type: none"> • Complete firmware version is shown 		
Bugfix	<ul style="list-style-type: none"> • 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.0.6		Release Date	04.03.2021
New Features	<ul style="list-style-type: none"> • 		
Bugfix	<ul style="list-style-type: none"> • Finds redundant CPUs again 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.0.5		Release Date	15.02.2021
New Features	<ul style="list-style-type: none"> • 		
Bugfix	<ul style="list-style-type: none"> • 		
Known Bugs	<ul style="list-style-type: none"> • Redundant CPUs are not displayed 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.0.4		Release Date	03.06.2020
New Features	<ul style="list-style-type: none"> • 		
Bugfix	<ul style="list-style-type: none"> • URL for web browser is changed for CPUs in SWU mode 		
Known Bugs	<ul style="list-style-type: none"> • 		
Remarks	<ul style="list-style-type: none"> • 		

V 2.0.3		Release Date	09.01.2020
New Features	•		
Bugfix	• Change support E-Mail address		
Known Bugs	•		
Remarks	•		

V 2.0.2		Release Date	20.03.2019
New Features	<ul style="list-style-type: none"> • Support for redundant CPUs • Encryption of sensible data • Added function to get service file 		
Bugfix	•		
Known Bugs	•		
Remarks	•		

V 1.16.0		Release Date	08.05.2018
New Features	• CPUs with critical alerts is highlighted red and ToolTip text indicates the error		
Bugfix	•		
Known Bugs	•		
Remarks	•		

V 1.15.0		Release Date	16.03.2018
New Features	• Add possibility to stop SWU mode		
Bugfix	•		
Known Bugs	•		
Remarks	• New feature only works with bootloader version V2.0.0		

V 1.14.0		Release Date	18.01.2018
New Features	• Encrypt ethernet data		
Bugfix	• Fix Windows firewall		
Known Bugs	•		
Remarks	•		

V 1.13.0		Release Date	15.01.2018
New Features	<ul style="list-style-type: none"> • Add right click menu on table items to open web browser • Append security hint to IP warning text. 		
Bugfix	•		
Known Bugs	• Windows firewall blocks communication ports		
Remarks	•		

V 1.12.2		Release Date	05.12.2017
New Features	•		
Bugfix	•		
Known Bugs	•		
Remarks	• Initial release		

Support: support.automation@r-stahl.com
+49 7942 943-4123
r-stahl.com